



Preserving the substance and significance of gravestones

IRVING SLAVID
Conservator
MARTIN JOHNSON
Conservator
PROF. NORMAN R. WEISS
Consultant

CONDITIONS SUMMARY,
CONSERVATION RECOMMENDATIONS
AND
CONDITION ASSESSMENTS

FOR

OLD BURYING GROUND
STONEHAM, MA

April 2012



INTRODUCTION

MCC inspected the Old Burying Ground on March 22, 27, and 28th 2012. The Town supplied a location map and a grid system was added to aid in locating the markers.

In general the cemetery is in good condition with minimal disturbance and has had very limited restoration work done in the past. The orientation of the stones is very unusual with many being perpendicular to one another. We do not have an explanation for this.

All markers and digital photographs were given a unique ID consisting of an alpha/numerical grid location and a figure relating to the number of markers within that grid. The grid is based on a forty foot plot. The previous identifying numbers done by the 2007 Boy Scout project) which was quite complete) for the headstones were kept and any accompanying footstones were numbered with the headstones' number followed by ".1", i.e. 87.1.

We inventoried a total of 490 markers, which included 146 footstones. Each stone was inspected and when conservation treatments were required, the condition was documented. All stones were digitally recorded and images identified with the alpha/numeric grid number. All headstones were measured and inscriptions noted.

While the majority of markers in the cemetery are stable, we listed 102 markers (65 headstones and 37 footstones) which will require future conservation treatments.

METAL "CAPPED" MARKERS

There are a great number of slates which have been "capped" with copper or metal coverings. These caps were meant to help prevent water from entering through small cracks and delaminations which are typically found in slates (and sandstones). Limiting the accumulation of water during freezing temperatures would thus reduce future expansion and ongoing deterioration of the stone. This was often tastefully done in the late 19th and early 20th century with thin strips of lead or copper. These early examples have now become a historical part of a cemetery.



*Caps in Old Burying Ground
Stoneham*



*Example of a historical lead cap
Hartford, CT*

Unfortunately the caps in the Old Burying Ground (which started in the late 1930's and continued up until 1950) are held on by bolts drilled through the stone. In many cases the caps obscure and deface the original carving. Aesthetically they diminish the overall quality of the cemetery.



*Original carving covered
and hole drilled through
angel motif (Oliver Richardson)*



Example of covering original carving

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

In a few cases where the bolts were loose we were able to tilt "open" the cap and note the condition of the stone.



There are no visible delaminations of this marker (Edward Bucknam)



Detail of hole

There are 64 slate markers that are "capped" in this way and otherwise appear to be stable. Because the capping was completed over 50 years ago, and can therefore be considered somewhat "historic", we recommend that representative examples of 5 to 7 caps remain and all the other caps removed. This sampling can be decided by the Stoneham Cemetery Commission. The condition of the slates can then be fully assessed, mounting holes can be properly filled and any voids caused by delaminations can be addressed.

There are additional "capped" markers that have other issues which require further conservation treatments. These are noted on the condition assessments.

CONDITIONS SUMMARY

The phased programming of work projects depends on a number of factors, including the severity (and progressive nature) of deterioration, and the nature and complexity of the required treatments. In most cases, the development of a monument conservation plan also incorporates non-technical priorities. This involves the defining of "value" in terms of the artistic quality and/or historic significance of individual monuments.

The primary consideration, however, is safety. A monument that is structurally unsound may pose an immediate danger to the cemetery worker, to the visitor, to itself, or to other monuments nearby. For most historic cemeteries, monuments surveyed can be placed into four technical categories, by priority:

- 1 hazardous—requires immediate action;
- 2 unstable deterioration—requires treatment as soon as possible;
- 3 ongoing deterioration—may require treatment in 2 to 5 years;
- 4 stable—no treatment required (re-inspect in 5-10 years).

Identification of individual monuments that are in hazardous condition is essential, as is the development of a plan to reduce the potential for damage and injury, and to remove the danger entirely.

During our inspection we discovered 102 markers whose condition required a condition assessment. More than half of these are tilted or sunken and are listed as priority #3. The 64 markers that were only capped, and only require their caps removed, holes filled and condition documented were not individually assessed at this time as the procedure would be identical for each.

The following are the totals of the study; a complete list with a brief condition description is attached:

Priority 1- Hazardous	7
Priority 2- Unstable	32
Priority 3- Ongoing Deterioration	63

Removal of caps (treatment when required) 64

While the capped markers do not exhibit "ongoing deterioration", we recommend the removal of the caps, filling of mounting holes and additional treatment when required (see "Filling of delaminations"- Page 15)

PHASED WORK SCHEDULE

If necessary, conservation work could be spread over 2-3 years.

Realistic conservation estimates at 2012 rates for a professional conservator following the requirements of the AIC Code of Ethics and Standards of Practice and in compliance with the Secretary of the Interior's Standards for the Treatment of Historic Properties.

Restoration to Priority 1 and 2 unstable markers (39):

\$23,000 to \$26,800

Restoration to Priority 3: 63 stones. All of these stones require resetting. Because of the proximity of trees and roots to many of the stones, some of these will be time consuming. (34 headstones, 29 footstones):

\$20,000 to \$22,000

Removing 64 metal caps, filling of holes and treatments when required:

\$11,000 to 13,500

Total budget: \$54,000 to \$62,300

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

PRIORITY 1- 7 Markers

Location	Type	ID	Last Name	First Name	Condition
E2.07	Headstone	2	Hay	Sarah	Fractured, probe
C4.33	Headstone	143	Bucknam	Reb??	Fragment, Tilted
A2.03	Headstone	81	Gould	James	Unstable- HAZARDOUS
D5.13	Headstone	153	Green	Jesse	Unstable- HAZARDOUS
C8.01	Headstone	272	Howard	Sarah/Mary	Unstable- HAZARDOUS
D4.10	Headstone	138	Wilson	Roxana	Unstable, HAZARDOUS
D5.14	Headstone	152	Winslow	Philena	Unstable, HAZARDOUS

PRIORITY 2- 32 Markers

Location	Type	ID	Last Name	First Name	Condition
D2.02	Footstone	16.1	Green	Rebekah	Against tree, reset
D3.12	Headstone	86	Gould	Daniel	Capped, Fractured
C4.26	Footstone	147.1	Gould	Mary	Delaminations
B4.02	Footstone	137.1	Hadley	David	Fallen, Reset
D2.09	Headstone	12	Green	Jonathan	Fractured
B2.09	Headstone	52	Vinton	Thomas	Fractured
B3.12	Headstone	68	Eaton	Anna	Fractured
C4.28	Footstone	146.1	Gould	Moley	Fractured
C5.02	Headstone	160	Simonds	Abigail	Fractured
B5.06	Headstone	200	Wiley	Sally	Fractured
B7.04	Footstone	224.1	Wright	Peter	Fractured
D8.11	Headstone	316	Stone	Aaron	Fractured
D8.11.1	Headstone	316	Stone	Clarissa	Fractured
D7.10	Headstone	328	Hill	John	Fractured
B8.21	Headstone	258	Rowe	Maria	Fractured, failed repair
D2.13	Headstone	10	Green	Rebec?	Fractured, probe
B3.04	Footstone	61.1	Hay	Peter	Fractured, probe
B3.13	Headstone	69	Vinton 3rd	Ezra	Fractured, probe
D7.13	Headstone	331	Green	Peter	Fractured, probe
C3.20	Headstone	95	Gould	David	Fragment
E5.02	Headstone	151	Richardson	Oliver	Fragment
C6.03	Headstone	192	Howard	Joshua	Overgrown, reset
D3.29	Headstone	105	Gould	Anna	Reset
D3.33	Headstone	120	Holdin	Anna	Reset
C4.30	Footstone	145.1	Gould	Mary	Reset
B6.04	Headstone	207	Hay	David	Reset
B6.05	Headstone	208	Hay	Aaron	Reset
B7.30	Headstone	253	Bryant	Harriet	Reset
C8.09	Headstone	280	Lynde	Charles	Reset
D3.11	Footstone	87.11	G.	A.	Reset Locate?
C8.04	Headstone	275	Lynde	Sarah	Reset to base
B6.14	Headstone	219	Hay	Mary	Tilted, fractured

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

PRIORITY 3- 63 Markers

Location	Type	ID	Last Name	First Name	Condition
C2.10	Headstone	30	Johnson	Sarah	7 degree tilt. Reversed?
C1.04	Headstone	23	Cleaveland	Abigail	Capped, Delaminations
C1.01	Headstone	25	Richardson	Reuben	Capped, Reversed, reset
B3.01	Headstone	59	Bryant	Polly	Capped, Tilted Reset
C4.31	Headstone	144	Bucknam	Edward	Capped, Tilted Reset
C4.08	Headstone	127	Green	Esther	Capped, Tilted, reset
C4.27	Headstone	146	Gould	Moley	Capped, Tilted, reset
D6.03	Headstone	187	Piper	Mary	Capped, Tilted, reset
B6.02	Headstone	205	Hay	Peter	Capped, Tilted, reset
B6.12	Headstone	213	Willy	James	Capped, Tilted, reset
B8.19	Headstone	256	Rowe	Phebe	Capped, Tilted, reset
D5.11	Headstone	154	Green	Jerusha	Old repair
D4.09	Footstone	140.1	Bucknam	John	Relocate behind #140
C7.14	Headstone	315	Larrabee	Hannah	Reset
D2.14	Footstone	9.1	Green	Infant son	Reset in proper location
C1.03	Footstone	24.1	Richardson	Esther	Reversed, reset
D8.19	Footstone	337.1	Green	Rebekah	Reversed, Reset
B8.25	Headstone	262	Green	Mother B.S.G.	Tilted, reset
B8.26	Headstone	263	Green	Father H.G.	Tilted, reset
B8.27	Headstone	264	Green	Mother A.G.G.	Tilted, reset
D8.15	Headstone	335	??		Tilted, reset
D2.04	Footstone	15.1	Green	Lydia	Tilted reset
A2.06	Footstone	77.1	Bucknam	Geo/Hannah	Tilted, reset
A2.05	Footstone	83.1	Gould	Hepzibah	Tilted Reset
C3.26	Footstone	92.1	Gould	Joseph	Tilted reset
C3.23	Footstone	94.1	Gould	Dorcas	Tilted Reset
C3.04	Footstone	110.1	Hay	Mehetable	Tilted reset
C4.32	Footstone	144.1	Bucknam	Edward	Tilted Reset
B2.04	Footstone	49.1	Vinton	Hannah	Tilted, reset
D3.18	Headstone	107	Hadley	John	Tilted, reset
D3.26	Footstone	112.1	Stevens	Nancy	Tilted, reset
D3.20	Footstone	115.1	Stevens	Henrietta	Tilted, reset
C3.33	Footstone	116.1	Stevens	Lora	Tilted, reset
C3.30	Footstone	118.1	Stevens	Elizabeth	Tilted, reset
D4.04	Footstone	121.1	Sprague	Samuel	Tilted, reset
C4.14	Footstone	124.1	Bucknam	Sarah	Tilted, reset
C4.11	Footstone	126.1	Green	Daniel	Tilted, reset
C4.09	Footstone	127	Green	Esther	Tilted, reset
C4.05	Footstone	129.1	Wright	Mary	Tilted, reset
C4.03	Footstone	130.1	Green	Daniel	Tilted, reset
D4.08	Headstone	139	Bucknam	Mary	Tilted, reset
C4.29	Headstone	145	Gould	Mary	Tilted, reset
D5.12	Footstone	154.1	Green	Jerusha	Tilted, reset

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

PRIORITY 3 - continued

Location	Type	ID	Last Name	First Name	Condition
D5.09	Headstone	155	Green	John	Tilted, reset
D5.10	Footstone	155.1	Green	John	Tilted, reset
D5.04	Headstone	168	Gerry	(children)	Tilted, reset
D5.02	Headstone	180	Richardson	Jonas	Tilted, reset
B6.03	Headstone	206	Hay	Dorcas	Tilted, reset
B7.13	Footstone	230.1	Richardson	Caleb	Tilted, reset
B8.02	Footstone	232.1	Richardson	Mary	Tilted, reset
B8.10	Footstone	236.1	Richardson	Anna	Tilted, reset
B7.20	Headstone	241	Hadley	Rebekah	Tilted, reset
B7.24	Headstone	244	Green	Daniel	Tilted, reset
B7.25	Footstone	244.1	Green	Daniel	Tilted, reset
B8.20	Headstone	257	Rowe	Louiza	Tilted, reset
B8.23	Headstone	260	Lynde	Horace	Tilted, reset
B8.28	Headstone	265	Green	Fidelia	Tilted, reset
C7.05	Headstone	271	Howard	John	Tilted, reset
C8.05	Headstone	276	Lynde	Moses/Warren	Tilted, reset
D8.05	Headstone	305	Stone	Joseph	Tilted, reset
D8.10	Headstone	308	Cowdrey	Betsey	Tilted, reset
B3.07	Footstone	63.1	Cutler	Jacob	Tilted, reversed setting
D9.05	Headstone	345	Brown	Laura/Susan	Tilted, roots

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

CAPPED STONES- 64 Markers*

Location	ID	Last Name	First	Location	ID	Last Name	First
D2.15	9	Green	Infant	B1.01	73	Gould	Abba
D2.05	14	Green	Jonathan	D3.09	87	Gould	Mary
D2.03	15	Green	Lydia	D3.07	88	Gould	Ebenezer
C1.10	18	Osgood	Lucy	D3.05	89	Gould	Ruth
C1.08	20	Hart	Sarah	D3.03	90	Gould	Daniel
C1.07	21	Bryant	Joseph	C3.18	96	Gould	Elizabeth
C1.06	22	Oliver	Abigail	D4.03	121	Sprague	Samuel
C2.08	28	Green	Daniel	C4.15	123	Bucknam	Lucy
C2.07	29.1	Green	Ruth	C4.13	124	Bucknam	Sarah
C3.01	31	Gould	Abraham	C4.10	126	Green	Daniel
C3.02	32	Gould	Mary	C4.06	128	Lynde	Judeth
B3.20	33	Wright	Timothy	C4.04	129	Wright	Mary
B3.21	34	Wright	Mary	C4.19	134	Brown	Sarah
B2.21	35	Knight	Hannah	C4.17	136	Sweetser	Phineas
C2.12	35.1	Knight	Hannah	C4.35	142	Bucknam	Anna
B2.22	36	Gould	Abigail	C4.25	147	Gould	Mary
B2.23	37	Gould	Daniel	C4.20	150	Hay	Isabel
B2.25	38	Gould	Sarah	D5.05	157	Geary	David
B2.26	38.1	S.G.		B4.03	162	Crooker	Polly
B2.27	39	Goold	Daniel	D5.19	164	Richardson	Oliver
B2.31	41	Hay	Ruth	D5.15	167	Richardson	Betty
B3.18	44	Hay	Sarah	C5.06	170	Geary	Lucinda
B1.06	47	Vinton	Thomas	C5.15	182	Holden	Ebenezer
B1.08	47.1	Vinton	Thomas	B5.04	198	Wiley	Susannah
B2.19	57	Noble	Mary	B7.12	230	Richardson	Caleb
B2.20	58	Noble	John	B8.01	232	Richardson	Mary
B3.02	60	Bryant	Jerusha	B8.09	236	Richardson	Anna
B3.05	62	Cutler	Elizabeth	B7.21	242	Hadley	Hannah
B3.06	63	Cutler	Jacob	B7.28	246	Green	Sarah
B3.08	64	Hay	Abigail	B7.31	254	Hill	James
B3.10	66	Hay	Peter	B7.32	255	Hill	Mary
B1.04	70	Gould	Thomas	C3.28	347	Parker	Ruth

***Note: the total number of capped stones in the Old Burying Ground is 75. 11 stones have been listed on pages 7 and 8 as needing treatment (1 priority 2 stone; 10 priority 3 stones), while the remaining 64 appear above.**

CONSERVATION RECOMMENDATIONS

CLEANING

In general, we do not recommend cleaning unless necessary to perform repairs. Most of the soiling is biological, and while it is slowly attacking the surface of the stone, most cleaning procedures are more aggressive than the micro-organism and additional surface material would be lost. In some instances, discoloration may be associated with the degradation of the older repair materials, such as iron fixings or unstable surface treatments.

Having all the stones clean is not historically accurate. Because of the wide range of death dates in the cemetery and continuing soiling, at no time in its history did all the stones appear "clean". Cleaning is a complicated issue involving both aesthetic and technical considerations.

In the case of marbles, cleaning does not necessarily make the inscriptions more legible, and many times the "whiteness" makes it harder to decipher. However removing the biogrowth from the slate stones will not make them appear "new". Thus, we do recommend cleaning some of the slates when required.

If cleaning is necessary we recommend D/2 Biological Solution (Cathedral Stone, Hanover, MD) follow manufacturer's instructions for application and fully rinse with water.

Removal of failed repairs

Repairs are considered as having failed if they are no longer functional, are unsightly, or have induced damage to adjacent original stone. Failed adhesives, mortars and pins require careful removal before proceeding with conservation treatment. Some temporary stabilization may be necessary as poorly attached fragments are disassembled.

Removal of degraded structural resins (and of the associated discoloration within the stone) may be particularly difficult and time-consuming. Mechanical removal is generally done with small hand tools. The cutting of pins and fasteners may require power tools. Ferrous metal pins are most often locked in place by corrosion expansion; their removal is best done by careful drilling with a properly-sized coring bit.

RESETTING

Eighteenth and early nineteenth century New England gravestones are typically long panels of stone that were set directly in the ground. By the first half of the 19th century, it appears that many headstones were set onto bases, some composed of several individual elements. Some bases were designed with a setting slot; others have pins. Although the re-setting of these stones is relatively straight-forward, inept handling practices can cause great harm.

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

For larger monuments, this work is considerably more complicated, and often involves the use of specialized lifting techniques.

Resetting in ground

Tilted stones sitting directly in the ground can be made plumb by careful excavation of soil with hand tools, to permit re-setting in the proper position. If there is not an adequate length of below grade material to adequately support the marker a new cast concrete below grade base will be required (See below: New cast concrete base).

Once the stone is carefully placed into vertical position at the proper depth, the stone is made plumb and level, and aligned with adjacent markers. Backfill with a mixture of sand and small gravel, wetted and compacted. Disturbed areas of the ground are re-graded with existing topsoil.

Resetting on/in existing base

Unsecured stones with existing bases should be re-set, but often require re-leveling and aligning of some or all base elements, and the removal of failed pins. For larger stones, which can weigh more than 300 pounds, lifting can be the most difficult and expensive portion of the operation. This work requires the careful use of hoisting equipment, and can be dangerous.

Re-setting is on a full bed of modified lime (or hydraulic lime) mortar, with fine sand; 3 parts cement, 2 parts high calcium lime and 8-10 parts fine sand (000 is preferred if available) all measured by volume. For maximum bond the mating surfaces should be primed with Acryl 60 diluted 1:3.

For more massive stones, small squares of thick lead sheet are used as corner shims, to establish a reasonable joint dimension, and for minor adjustments to level. Pins, if required, should be threaded stainless steel, 10 to 25 mm in diameter for most situations. They are secured in a moisture-insensitive structural adhesive or mortar.

Stones that require insertion into existing slotted bases can be set with the same mortar mix 3:2:8 as above made fluid with a high-range water reducer. This is poured and/or injected into the base slot. Stones are set plumb and level, and are braced for a minimum of three days to limit movement during curing of the grout.

Resetting into new cast concrete base

Fractures at (or just below) grade are relatively common for thinner headstones, but the success of structural adhesion in these situations is limited. In the past, the upper portions of these monuments have simply been inserted further into the ground. A better solution is the fabrication of a new below-grade base, to re-set the stone at a more reasonable height, allowing for the viewing of inscriptions and decoration. These are fabricated on site by casting in the ground with concrete, using a removable form insert to create a setting slot (½" thicker and 1" wider

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

than the marker, 1" deep); the finished top surface of the base should be entirely concealed by new topsoil, which is then seeded.

The bases are minimally 12 inches deep, 12 inches greater in thickness and 6 inches wider than the stone itself. Once the concrete has cured, forms are removed and the stones are reset into the slot as above.



On left, a new base partially filled with concrete and foam setting form in background.



Above, the poured base with setting form in place

When lower fragments are missing or there is a fracture at or below grade the lower edge of the stone may have to be re-squared prior to re-setting keeping losses at a minimum. Any inscriptions that will be lost or hidden are to be recorded.

REPAIR

Repair programs deal with the reassembly of fractures, and the filling of open joints, cracks and delaminations, and larger areas of materials loss. Most broken stones can be re-assembled with structural adhesives. Depending on the geometry of the break, reinforcement with pins may or may not be required.

Structural adhesion

Potential bonding surfaces are carefully cleaned and the pieces dry fitted to test for conformation, identifying contact areas. All fragments found nearby should be examined at this point; systematic soil probing in the general vicinity is frequently successful in locating missing pieces. (As noted earlier, structural adhesives do not perform adequately when used below or near grade.)

A thixotropic, moisture-insensitive two-part epoxy (Aboweld 55-22, Abatron) is applied along both surfaces of the glue line, keeping the adhesive slightly back from the edge of the break. Most of these adhesives require a minimum air and surface temperature of 10° C. Properly-aligned fragments are joined with clamps, and the assembly braced during curing of the epoxy. Any excess adhesive flowing from the glue lines should be allowed to partially cure, then carefully cut or chipped away with sharp hand tools. A recent fracture of sound material generally

requires less epoxy than a weathered surface with poorer "fit". When fully cured, areas along the glue line are concealed with a lime-based repair mortar.

Reinforcement

The extensive and routine use of pinning to repair fractured stones is controversial. There are many variables to consider before drilling. The cross-section of stone, the type of stone and soundness of material, and the location and shape of the fracture can all influence the decision to reinforce a structural repair. If the fractured stone is sound and/or recently broken, the attachment of fragments with a structural adhesive should be sufficient. As a general rule, slate, a sedimentary material, should not be drilled for pins.

The use of pins has sometimes been recommended to provide a "slow failure" if the adhesive should fail in the future. This assumes that if the monument were to fail again it would be along the previous failure line. This may or may not be the case. In fact, the use of pins can increase the length of the moment arm when force is applied at some distance from the repair. This means that a lesser force can fracture the stone, and that failure will not occur at the glue line, but rather at the end of the pins.

Complex breaks, however, may require some drilling and structural pinning for safer reassembly. If there are missing fragments, voids can be spanned by these pins to provide an armature for the subsequent installation of repair mortars.

Where pinning is required, holes should be drilled at slow speed, using an appropriately sized masonry bit. Water should be liberally applied into the hole while drilling. Before inserting pins, the drilling debris should be thoroughly flushed out with water and the hole allowed to dry fully, or (alternatively) blown clean with compressed air. The drilling of holes into the edge of a weak, deteriorated stone may be very destructive, and is often impossible.

Threaded stainless steel rods are recommended for pinning. The diameter of the drill hole should be less than 1/3 of the thickness of the stone, and the total length of the pin equal to 6 to 10 times its diameter. Pins are secured in a moisture-insensitive structural adhesive.

Repair mortars/ crack fillers

Losses designated for compensation can be filled with commercially-available cementitious restoration mortars (Jahn Restoration Mortars, Repical, both from Cathedral Stone), or a pigmented lime mortar, using colored aggregates. Mortar color and texture should be matched to that of the unsoiled stone, seen after cleaning or (more often) where fractured. If the stone will not be cleaned, artificial "soiling" of the cured mortar surfaces can be done by a variety of means, including use of a pigmented, transparent potassium silicate coating (Silin, Cathedral Stone), or a diluted acrylic dispersion). Dry colors for this purpose and for

**Old Burying Ground, Stoneham, MA,
Condition Summary and Conservation Recommendations**

incorporation into the mortar itself must be alkali-stable oxides, as used in the construction industry.

These materials and methods are also useful for crack filling. In this instance, however, the aggregates must be considerably finer in size. As for pointing, work with repair mortars should not be undertaken when there is a risk of freezing temperatures in the following 14 days.

Filling of delaminations

Repair of delamination is designed to prevent further detachment of stone, by re-establishing cohesion between foliated layers, and preventing the penetration of water.

Best practice begins with the careful removal of loose debris in the voids, using hand tools and the cautious use of compressed air. Interior surfaces are then saturated with a wetting solution, such as isopropanol/water

Filling voids caused by delaminations in slates is challenging. The dark stone is subject to considerable expansion and contraction due to temperature changes, and any filled voids will be subject to continued compression and tension.

Historically, commercially available grouts (M-40 Cathedral Stone), or a low strength cement/lime (3:2:8) grout, with fine aggregates have been used to fill the voids. However, these cementitious grouts will typically fail in short time in most slates because of the movement of each foliated layer of stone.

Promising tests filling the top areas of the voids with a pigmented flexible elastomeric sealant such as Dow 756 or Sto 80214 have been ongoing and appear successful. Immediate cleanup is important and necessary. While these field trials are still ongoing, the likelihood of failure is less than with a rigid fill. The issue of "retreatability" has to be weighed against total "failure".

In either case, open foliated layers on the sides of the stone are not filled to allow any water that may become entrapped to escape. For large voids, backer rods are required before grouting.

PRODUCTS/SUPPLIERS

- *RepliCal™
- *Jahn™ Restoration Mortars
- *M-40 Flowable grouts
- *Silin
- * D/2 Biological Solution
from: Cathedral Stone Products Inc.
7266 Park Circle Drive
Hanover MD 21076 USA
800 684 0901 fax 800 684 0904

- *Dow Corning 756 Building Sealant
From: Dow Corning Corporation
Corporate Center
PO Box 994
MIDLAND MI 48686-0994
United States

- *Sto 80214 Flexible Crack Filler
From: Sto Corporation
3800 Camp Creek Parkway
Building 1400, Suite 120
Atlanta, Georgia 30331
Phone: (800) 221-2397

- *Aboweld 55-22
from: Abatron Inc
5501 95th Avenue
Kenosha, WI 53144
262 653 2000 fax 262 653 2019

CONDITION ASSESSMENT Inspection Date: 3/22-28/2012 By: IS & MJ

MONUMENT CONSERVATION COLLABORATIVE LLC
PO Box 541, Norfolk, CT 06058 860 307 6695 MCCLLC@gmail.com

Cemetery: Old Burying Ground, Stoneham, MA

NAME ON MARKER **H.B. G. B. (George and Hannah Buckman)**

Death Date: Material: **slate** Marker Type: **Footstone**

Condition of Inscription: **decipherable**

EXISTING CONDITIONS	CONSERVATION STRATEGY
Tilted	Reset

CONSERVATION PRIORITY

3

1) Hazardous, immediate action 2) Unstable- asap
3) Ongoing deterioration, treat 2-5 years 4) Stable
A) Artistic H) Historical P) Visually prominent M) Monitor

RECOMMENDED TREATMENT

1. Excavate footstone; remove soil from setting area to appropriate depth.
2. Remove soiling by light brushing with nylon brushes and water
3. Re-set footstone plumb at appropriate height and level onto gravel bed, aligned with adjacent markers
4. Backfill area around footstone with tamped sand and gravel
5. Re-grade disturbed areas with existing topsoil.

Comments:

All information given and recommendations made herein are based upon our research and are believed to be accurate, but no guarantee, either expressed or implied, is made with respect thereto. © MONUMENT CONSERVATION COLLABORATIVE LLC



Size

Exist # **77.1**

Location: **A2.06**

CONDITION ASSESSMENT Inspection Date: 3/22-28/2012 By: IS & MJ

MONUMENT CONSERVATION COLLABORATIVE LLC
PO Box 541, Norfolk, CT 06058 860 307 6695 MCCLLC@gmail.com

Cemetery: **Old Burying Ground, Stoneham, MA**

NAME ON MARKER **E.A.S. (Elizabeth Stevens)**

Death Date: Material: **Marble** Marker Type: **Footstone**

Condition of Inscription: **Legible**

EXISTING CONDITIONS	CONSERVATION STRATEGY
Tilted	Reset

CONSERVATION PRIORITY 3

1) Hazardous, immediate action 2) Unstable- asap
 3) Ongoing deterioration, treat 2-5 years 4) Stable
 A) Artistic H) Historical P) Visually prominent M) Monitor

RECOMMENDED TREATMENT
<ol style="list-style-type: none"> 1. Excavate footstone; remove soil from setting area to appropriate depth. 2. Remove soiling by light brushing with nylon brushes and water 3. Re-set footstone plumb at appropriate height and level onto gravel bed, aligned with adjacent markers 4. Backfill area around footstone with tamped sand and gravel 5. Re-grade disturbed areas with existing topsoil.

Comments:

All information given and recommendations made herein are based upon our research and are believed to be accurate, but no guarantee, either expressed or implied, is made with respect thereto. © MONUMENT CONSERVATION COLLABORATIVE LLC



Size

Exist # **118.1**

Location: **C3.30**

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C1.11	Headstone	1	Nason	Dudley	n.a.		C1.11.jpg	Marble	12x4x18
E2.07	Headstone	2	Hay	Sarah	10/25/1839		E2.07.jpg	Slate	33x2
E2.08	Footstone	2.1	Hay	Sarah			E2.08.jpg	Slate	
E2.05	Headstone	3	Hay	David	8/4/1813		E2.05.jpg	Slate	33x1.5x48
E2.06	Footstone	3.1	Hay	David			E2.06.jpg	Slate	
E2.03	Headstone	4	Green	Sarah	10/6/1836		E2.03.jpg	Slate	28x2x48
E2.04	Footstone	4.1	Green	Sarah			E2.04.jpg	Slate	
E2.01	Headstone	5	Green	Jesse	1/31/1799		E2.01.jpg	Slate	30x2x49
E2.02	Footstone	5.1	Green	Jesse			E2.02.jpg	Slate	
D2.19	Headstone	6	Green	Dorcas	9/3/1833		D2.19.jpg	Slate	26x2x50
D2.20	Footstone	6.1	Green	Dorcas			D2.20.jpg	Slate	
D2.17	Headstone	7	Green	Jonathan	3/1/1820		D2.17.jpg	Slate	30x2x51
D2.18	Footstone	7.1	Green	Jonathan			D2.18.jpg	Slate	
D2.16	Headstone	8	Green	Jonathan	11/9/1775		D2.16.jpg	Slate	15x1x19
D2.15	Headstone	9	Green	Infant son	Oct. ?		D2.15.jpg	Slate	14x1.5x13
D2.14	Footstone	9.1	Green	Infant son			D2.14.jpg	Slate	
D2.13	Headstone	10	Green	Rebec?	11/9/175?		D2.13.jpg	Slate	15x1.5
D2.11	Headstone	11	Green	Rebekah	7/20/1786		D2.11.jpg	Slate	22x1.5x29
D2.12	Footstone	11.1	Green	Rebekah			D2.12.jpg	Slate	
D2.09	Headstone	12	Green	Jonathan	1795		D2.09.jpg	Slate	24x1.5
D2.10	Footstone	12.1	Green	Jonathan			D2.10.jpg	Slate	
D2.07	Headstone	13	Green	Sarah	2/26/1745		D2.07.jpg	Slate	27x3x33
D2.08	Footstone	13.1	Green	Sarah			D2.08.jpg	Slate	
D2.05	Headstone	14	Green	Jonathan	7/21/1744		D2.05.jpg	Slate	28x3x30
D2.06	Footstone	14.1	Green	Jonathan			D2.06.jpg	Slate	
D2.03	Headstone	15	Green	Lydia	8/28/1775		D2.03.jpg	Slate	23x1.5x37
D2.04	Footstone	15.1	Green	Lydia			D2.04.jpg	Slate	
D2.01	Headstone	16	Green	Rebekah	10/5/1750		D2.01.jpg	Slate	16x1x18

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription Photo	Stone	Size (inches)
D2.02	Footstone	16.1	Green	Rebekah		D2.02.jpg	Slate	
D1.01	Footstone	17.1	Nichols	Lydia	1776	D1.01.jpg	Slate	
C1.10	Headstone	18	Osgood	Lucy	3/5/1776	C1.10.jpg	Slate	22x3x31
C2.05	Footstone	18.1	Osgood	Lucy		C2.05.jpg	Slate	
C1.09	Headstone	19	Osgood	James	3/2/1745	C1.09.jpg	Slate	31x4x33
C2.04	Footstone	19.1	Osgood	James		C2.04.jpg	Slate	
C1.08	Headstone	20	Hart	Sarah	8/11/1801	C1.08.jpg	Slate	27x1.5x33
C2.03	Footstone	20.1	Hart	Sarah		C2.03.jpg	Slate	
C1.07	Headstone	21	Bryant	Joseph	4/14/1810	C1.07.jpg	Slate	30x2x44
C2.02	Footstone	21.1	Bryant	Joseph		C2.02.jpg	Slate	
C1.06	Headstone	22	Oliver	Abigail	7/3/1791	C1.06.jpg	Slate	24x3x30
C2.01	Footstone	22.1	Oliver	Abigail		C2.01.jpg	Slate	
C1.04	Headstone	23	Cleaveland	Abigail	6/3/1793	C1.04.jpg	Slate	27x2x45
C1.05	Footstone	23.1	Cleaveland	Abigail		C1.05.jpg	Slate	
C1.02	Headstone	24	Richardson	Esther	2/8/1809	C1.02.jpg	Slate	21x2x29
C1.03	Footstone	24.1	Richardson	Esther		C1.03.jpg	Slate	
C1.01	Headstone	25	Richardson	Reuben	12/22/1776	C1.01.jpg	Slate	23x2x29
B1.11	Headstone	26	Richardson	Caleb	4/28/1772	B1.11.jpg	Slate	16x1.5x17
B1.12	Footstone	26.1	Richardson	Caleb		B1.12.jpg	Slate	
E2.09	Headstone	27	Horn	Pamela	6/14/1855	E2.09.jpg	Marble	15x2x34
C2.08	Headstone	28	Green	Daniel	10/26/1745	C2.08.jpg	Slate	25x2x34
C2.09	Footstone	28.1	Green	Daniel		C2.09.jpg	Slate	
C2.06	Headstone	29	Green	Ruth	11/3/1770	C2.06.jpg	Slate	25x3x25
C2.07	Footstone	29.1	Green	Ruth		C2.07.jpg	Slate	
C2.10	Headstone	30	Johnson	Sarah	12/9/1862	C2.10.jpg	Marble	20x2x33
C2.11	Footstone	30.1	Johnson	Sarah		C2.11.jpg	Marble	
C3.01	Headstone	31	Gould	Abraham	9/4/1776	C3.01.jpg	Slate	23x1.5x32
C3.02	Headstone	32	Gould	Mary	8/5/1764	C3.02.jpg	Slate	23x1.5x28

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
B3.20	Headstone	33	Wright	Timothy	2/10/1728		B3.20.jpg	Slate	27X3X28
B3.21	Headstone	34	Wright	Mary	10/27/1755		B3.21.jpg	Slate	26x3x33
B2.21	Headstone	35	Knight	Hannah	5/14/1763		B2.21.jpg	Slate	21x2x28
C2.12	Footstone	35.1	Knight	Hannah			C2.12.jpg	Slate	
B2.22	Headstone	36	Gould	Abigail	1/9/1771		B2.22.jpg	Slate	20x1x30
B2.23	Headstone	37	Gould	Daniel	3/7/1761		B2.23.jpg	Slate	26x1.5x35
B2.24	Footstone	37.1	Gould	Daniel			B2.24.jpg	Slate	
B2.25	Headstone	38	Gould	Sarah	12/4/1745		B2.25.jpg	Slate	26x3x34
B2.26	Footstone	38.1	Gould	Sarah			B2.26.jpg	Slate	
B2.27	Headstone	39	Goold	Daniel	10/25/1734		B2.27.jpg	Slate	20x2x26
B2.28	Footstone	39.1	Goold	Daniel			B2.28.jpg	Slate	
B2.29	Headstone	40	Briant	Sarah	7/16/1741		B2.29.jpg	Slate	15x2x16
B2.30	Footstone	40.1	Briant	Sarah			B2.30.jpg	Slate	
B2.31	Headstone	41	Hay	Ruth	7/10/1748		B2.31.jpg	Slate	27x3x37
B2.32	Footstone	41.1	Hay	Ruth			B2.32.jpg	Slate	
B3.14	Headstone	42	Hay	John	3/4/1730		B3.14.jpg	Slate	25x2x32
B3.15	Footstone	42.1	Hay	John			B3.15.jpg	Slate	
B3.16	Headstone	43	Hay	Peter	4/1/1748		B3.16.jpg	Slate	29x3x38
B3.17	Footstone	43.1	Hay	Peter			B3.17.jpg	Slate	
B3.18	Headstone	44	Hay	Sarah	3/3/1729		B3.18.jpg	Slate	26x2x29
B3.19	Footstone	44.1	Hay	Sarah			B3.19.jpg	Slate	
B1.09	Headstone	45	Baldwin	Timothy	12/3/1750		B1.09.jpg	Slate	27x3x34
B1.10	Footstone	45.1	Baldwin	Timothy			B1.10.jpg	Slate	
B1.05	Headstone	46	Vinton	Mary	2/15/1791		B1.05.jpg	Slate	24x2x33
B1.07	Footstone	46.1	Vinton	Mary			B1.07.jpg	Slate	
B1.06	Headstone	47	Vinton	Thomas	3/22/1763		B1.06.jpg	Slate	24x2x27
B1.08	Footstone	47.1	Vinton	Thomas			B1.08.jpg	Slate	
B2.01	Headstone	48	Vinton	Timothy	12/29/1836		B2.01.jpg	Slate	29x2x58

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription Photo	Stone	Size (inches)
B2.02	Footstone	48.1	Vinton	Timothy		B2.02.jpg	Slate	
B2.03	Headstone	49	Vinton	Hannah	4/1/1804	B2.03.jpg	Slate	
B2.04	Footstone	49.1	Vinton	Hannah		B2.04.jpg	Slate	23x2x46
B2.05	Headstone	50	Vinton	Thomas	2/16/1828	B2.05.jpg	Slate	30x2x50
B2.06	Footstone	50.1	Vinton	Thomas		B2.06.jpg	Slate	
B2.07	Headstone	51	Vinton	Mary	6/16/1832	B2.07.jpg	Slate	30x2x48
B2.08	Footstone	51.1	Vinton	Mary		B2.08.jpg	Slate	
B2.09	Headstone	52	Vinton	Thomas	12/31/1891	B2.09.jpg	Marble	12x5x28
B2.13	Headstone	53	Bryant	Daniel	3/9/1779	B2.13.jpg	Slate	20x1.5x29
B2.14	Footstone	53.1	Bryant	Daniel		B2.14.jpg	Slate	
B2.15	Headstone	54	Bryant	Daniel	7/17/1829	B2.15.jpg	Slate	21x2x42
B2.16	Footstone	54.1	Bryant	Daniel		B2.16.jpg	Slate	
B2.17	Headstone	55	Bryant	Mary	1/25/1862	B2.17.jpg	Slate	22x1.5x46
B2.18	Headstone	56	Bryant	Catherine	12/1/1826	B2.18.jpg	Slate	18x1.5x32
B2.19	Headstone	57	Noble	Mary	3/21/1813	B2.19.jpg	Slate	21x1.5x42
B2.20	Headstone	58	Noble	John	6/1/1889	B2.20.jpg	Slate	21x1.5x42
B3.01	Headstone	59	Bryant	Polly	4/3/1788	B3.01.jpg	Slate	12x1x28
B3.02	Headstone	60	Bryant	Jerusha	12/23/1782	B3.02.jpg	Slate	12X1x20
B3.03	Headstone	61	Hay	Peter	3/7/1790	B3.03.jpg	Slate	25x3x31
B3.04	Footstone	61.1	Hay	Peter		B3.04.jpg	Slate	
B3.05	Headstone	62	Cutler	Elizabeth	4/18/1825	B3.05.jpg	Slate	27x1.5x42
B3.06	Headstone	63	Cutler	Jacob	2/15/1805	B3.06.jpg	Slate	28x2x42
B3.07	Footstone	63.1	Cutler	Jacob		B3.07.jpg	Slate	
B3.08	Headstone	64	Hay	Abigail	11/7/1767	B3.08.jpg	Slate	18X2x34
B3.09	Headstone	65	Cutler	John	6/4/1792	B3.09.jpg	Slate	31x1.5x39
B3.10	Headstone	66	Hay	Peter	9/12/1764	B3.10.jpg	Slate	25x1x25
B3.11	Headstone	67	Hay	James	5/19/1781	B3.11.jpg	Slate	20x2x19
B3.12	Headstone	68	Eaton	Anna	11/9/1779	B3.12.jpg	Slate	20x1x14

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
B3.13	Headstone	69	Vinton 3rd	Ezra	8/10/1810		B3.13.jpg	Slate	16x1
B1.04	Headstone	70	Gould	Thomas	9/22/1838		B1.04.jpg	Slate	
B2.12	Footstone	70.1	Gould	Thomas			B2.12.jpg	Slate	
B1.03	Headstone	71	Gould	Hannah	9/1/1828		B1.03.jpg	Slate	26x2x52
B2.11	Footstone	71.1	Gould	Hannah			B2.11.jpg	Slate	
B1.02	Headstone	72	Gould	Susanna	8/2/1837		B1.02.jpg	Slate	25x1.5x56
B2.10	Footstone	72.1	Gould	Susanna			B2.10.jpg	Slate	
B1.01	Headstone	73	Gould	Abba	9/14/1843		B1.01.jpg	Slate	13x1.5x26
A1.04	Headstone	74	Gould	Phebe	4/13/1858		A1.04.jpg	Slate	24x2x49
A2.09	Footstone	74.1	Gould	Phebe			A2.09.jpg	Slate	
A1.03	Headstone	75	Gould	Jacob	3/20/1859		A1.03.jpg	Slate	24x2x50
A2.08	Footstone	75.1	Gould	Jacob			A2.08.jpg	Slate	
A1.02	Headstone	76	Gould	Hannah	5/18/1871		A1.02.jpg	Marble	22x3x44
A2.07	Footstone	76.1	Gould	Hannah			A2.07.jpg	Marble	
A1.01	Headstone	77	Bucknam	Geo/Hannah	862;3/9/1860		A1.01.jpg	Slate	28x2x40
A2.06	Footstone	77.1	Bucknam	Geo/Hannah			A2.06.jpg	Slate	
A2.12	Headstone	78	Gould	Levi/Elizabeth	850;4/1/1849		A2.12.jpg	Marble	20x3x46
A2.10	Headstone	79	Gould	Thomas	6/5/1848		A2.10.jpg	Marble	22x2x55
A2.11	Footstone	79.1	Gould	Thomas			A2.11.jpg	Marble	
A2.04	Headstone	80	??	One Little Henry	??		A2.04.jpg	Marble	12x1.5x16
A2.03	Headstone	81	Gould	James	6/14/18??		A2.03.jpg	Marble	22x5x38
A2.02	Headstone	82	Gould	Hepzibah	3/9/1866		A2.02.jpg	Marble	22x5x38
A2.01	Headstone	83	Gould	Hepzibah	12/18/1832		A2.01.jpg	Marble	24x2x47
A2.05	Footstone	83.1	Gould	Hepzibah			A2.05.jpg	Marble	
D3.16	Headstone	84	Gould	Daniel	5/1/1831		D3.16.jpg	Slate	28x2x39
D3.17	Footstone	84.1	Gould	Daniel			D3.17.jpg	Slate	
D3.14	Headstone	85	Gould	Eunice	2/27/1826		D3.14.jpg	Slate	27x2x46
D3.15	Footstone	85.1	Gould	Eunice			D3.15.jpg	Slate	

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
D3.12	Headstone	86	Gould	Daniel	3/14/1797		D3.12.jpg	Slate	31x1.5x35
D3.13	Footstone	86.1	Gould	Daniel			D3.13.jpg	Slate	
D3.09	Headstone	87	Gould	Mary	6/3/1793		D3.09.jpg	Slate	22x2x36
D3.10	Footstone	87.1	Gould	Mary			D3.10.jpg	Slate	
D3.11	Footstone	87.11	G.	A.			D3.11.jpg	Slate	
D3.07	Headstone	88	Gould	Ebenezer	8/8/1790		D3.07.jpg	Slate	22x1.5x21
D3.08	Footstone	88.1	Gould	Ebenezer			D3.08.jpg	Slate	
D3.05	Headstone	89	Gould	Ruth	8/22/1758		D3.05.jpg	Slate	23x1.5x31
D3.06	Footstone	89.1	Gould	Ruth			D3.06.jpg	Slate	
D3.03	Headstone	90	Gould	Daniel	3/8/1788		D2.03.jpg	Slate	26.5x1.5x33
D3.04	Footstone	90.1	Gould	Daniel			D3.04.jpg	Slate	
D3.01	Headstone	91	Gould	Susanna	3/29/1757		D3.01.jpg	Slate	23x2x21
D3.02	Footstone	91.1	Gould	Susanna			D3.02.jpg	Slate	
C3.25	Headstone	92	Gould	Joseph	9/25/1730		C3.25.jpg	Slate	13x1x14
C3.26	Footstone	92.1	Gould	Joseph			C3.26.jpg	Slate	
C3.24	Headstone	93	Gould	Mary	1/21/1791		C3.24.jpg	Slate	15x1.5x20
C3.22	Headstone	94	Gould	Dorcas	6/5/1730		C3.22.jpg	Slate	18x2x19
C3.23	Footstone	94.1	Gould	Dorcas			C3.23.jpg	Slate	
C3.20	Headstone	95	Gould	David	??		C3.20.jpg	Slate	
C3.21	Footstone	95.1	Gould	David			C3.21.jpg	Slate	
C3.18	Headstone	96	Gould	Elizabeth	4/18/1753		C3.18.jpg	Slate	23x3x24
C3.19	Footstone	96.1	Gould	Elizabeth			C3.19.jpg	Slate	
C3.16	Headstone	97	Gould	Elizabeth	8/6/1775		C3.16.jpg	Slate	21x2x40
C3.17	Footstone	97.1	Gould	Elizabeth			C3.17.jpg	Slate	
C3.14	Headstone	98	Gould	Jacob	6/14/1801		C3.14.jpg	Slate	22x2x38
C3.15	Footstone	98.1	Gould	Jacob			C3.15.jpg	Slate	
C3.12	Headstone	99	Gould	Jacob	11/25/1819		C3.12.jpg	Slate	31x2x60
C3.13	Footstone	99.1	Gould	Jacob			C3.13.jpg	Slate	

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C3.10	Headstone	100	Gould	David	7/6/1834		C3.10.jpg	Slate	29x2x58
C3.11	Footstone	100.1	Gould	David			C3.11.jpg	Slate	
C3.09	Headstone	101	Gould	Mary	11/21/1836		C3.09.jpg	Slate	22x2x56
E3.01	Headstone	102	Holden	Elizabeth	4/2/1841		E3.01.jpg	Slate	22x1.5x28
D3.32	Headstone	103	Gould	Dorcas	10/13/1831		D3.32.jpg	Slate	21.5x1.5x33
D3.30	Headstone	104	Gould	Joseph	11/1801		D3.30.jpg	Marble	24x2x27
D3.31	Footstone	104.1	Gould	Joseph			D3.31.jpg	Marble	
D3.29	Headstone	105	Gould	Anna	??		D3.29.jpg	Marble	12x2x25
D3.28	Headstone	106	Gould	David	2/17/1834		D3.28.jpg	Slate	22x2x40
D3.18	Headstone	107	Hadley	John	9/18/1746		D3.18.jpg	Slate	17x1.5x19
C3.07	Headstone	108	Hay	Mary	9/1/1741		C3.07.jpg	Slate	14x2x19
C3.08	Footstone	108.1	Hay	Mary			C3.08.jpg	Slate	
C3.05	Headstone	109	Hay	Ann	8/19/1741		C3.05.jpg	Slate	17x2x18
C3.06	Footstone	109.1	Hay	Ann			C3.06.jpg	Slate	
C3.03	Headstone	110	Hay	Mehetable	8/17/1741		C3.03.jpg	Slate	16x2x16
C3.04	Footstone	110.1	Hay	Mehetable			C3.04.jpg	Slate	
D3.27	Headstone	111	Stevens	(infant)	1/17/??		D3.27.jpg	Slate	12x2x15
D3.25	Headstone	112	Stevens	Nancy	10/6/1823		D3.25.jpg	Slate	17x3x33
D3.26	Footstone	112.1	Stevens	Nancy			D3.26.jpg	Slate	
D3.23	Headstone	113	Stevens	Charlotte	6/15/1817		D3.23.jpg	Slate	22x1.5x33
D3.24	Footstone	113.1	Stevens	Charlotte			D3.24.jpg	Slate	
D3.21	Headstone	114	Stevens	Philenia	3/29/1898		D3.21.jpg	Slate	21x2x31
D3.22	Footstone	114.1	Stevens	Philenia			D3.22.jpg	Slate	
D3.19	Headstone	115	Stevens	Henrietta	12/26/1816		D3.19.jpg	Slate	21x2x31
D3.20	Footstone	115.1	Stevens	Henrietta			D3.20.jpg	Slate	
C3.32	Headstone	116	Stevens	Lora	9/2/1817		C3.32.jpg	Slate	21x1.5x35
C3.33	Footstone	116.1	Stevens	Lora			C3.33.jpg	Slate	
C3.31	Headstone	117	Stevens	John	8/9/1851		C3.31.jpg	Marble	27x4x52

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C3.29	Headstone	118	Stevens	Elizabeth	8/7/1833		C3.29.jpg	Marble	26x2.5x50
C3.30	Footstone	118.1	Stevens	Elizabeth			C3.30.jpg	Marble	
D3.33	Headstone	120	Holden	Anna	6/18/1731		D3.33.jpg	Slate	14x1.5x18
D4.03	Headstone	121	Sprague	Samuel	5/7/1753		D4.03.jpg	Slate	26x3x24
D4.04	Footstone	121.1	Sprague	Samuel			D4.04.jpg	Slate	
D4.01	Headstone	122	Sprague	Joanna	6/17/1759		D4.01.jpg	Slate	24x2x25
D4.02	Footstone	122.1	Sprague	Joanna			D4.02.jpg	Slate	
C4.15	Headstone	123	Bucknam	Lucy	10/30/1799		C4.15.jpg	Slate	22x1.5x37
C4.16	Footstone	123.1	Bucknam	Lucy			C4.16.jpg	Slate	
C4.13	Headstone	124	Bucknam	Sarah	6/19/1780		C4.13.jpg	Slate	23x1.5x33
C4.14	Footstone	124.1	Bucknam	Sarah			C4.14.jpg	Slate	
C4.12	Headstone	125	Bucknam	William	10/23/1750		C4.12.jpg	Slate	15x1x23
C4.10	Headstone	126	Green	Daniel	8/15/1759		C4.10.jpg	Slate	29x2x35
C4.11	Footstone	126.1	Green	Daniel			C4.11.jpg	Slate	
C4.08	Headstone	127	Green	Esther	2/26/1747		C4.08.jpg	Slate	19x6x33
C4.09	Footstone	127	Green	Esther			C4.09.jpg	Slate	
C4.06	Headstone	128	Lynde	Judeth	2/4/1735		C4.06.jpg	Slate	26x3x24
C4.07	Footstone	128.1	Lynde	Judeth			C4.07.jpg	Slate	
C4.04	Headstone	129	Wright	Mary	6/20/1787		C4.04.jpg	Slate	20x1.5x22
C4.05	Footstone	129.1	Wright	Mary			C4.05.jpg	Slate	
C4.02	Headstone	130	Green	Daniel	4/28/1818		C4.02.jpg	Slate	31x2x58
C4.03	Footstone	130.1	Green	Daniel			C4.03.jpg	Slate	
C4.01	Headstone	131	Green	Joanna	9/27/1839		C4.01.jpg	Slate	20x2x46
D4.06	Headstone	132	Sprague	Anna	4/21/1809		D4.06.jpg	Slate	27x2x30
D4.05	Headstone	133	Sprague	Samuel	5/30/1803		D4.05.jpg	Slate	29x2.5x29
C4.19	Headstone	134	Brown	Sarah	5/6/1769		C4.19.jpg	Slate	21x1.5x30
C4.18	Headstone	135	Sweetser	Mary	3/27/1813		C4.18.jpg	Slate	26x1.5x30
C4.17	Headstone	136	Sweetser	Phineas	9/24/1764		C4.17.jpg	Slate	26x3x27

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
B4.01	Headstone	137	Hadley	David	5/29/1805		B4.01.jpg	Slate	20x2x38
B4.02	Footstone	137.1	Hadley	David			B4.02.jpg	Slate	
D4.10	Headstone	138	Wilson	Roxana	1897		D4.10.jpg	Granite	18x9x21
D4.08	Headstone	139	Bucknam	Mary	2/6/1861		D4.08.jpg	Slate	21x1.5x40
D4.07	Headstone	140	Bucknam	John	10/10/1861		D4.07.jpg	Slate	30x2x55
D4.09	Footstone	140.1	Bucknam	John			D4.09.jpg	Slate	
C4.36	Headstone	141	Bucknam	John	8/2/1803		C4.36.jpg	Slate	29x1.5x43
C4.37	Footstone	141.1	Bucknam	John			C4.37.jpg	Slate	
C4.35	Headstone	142	Bucknam	Anna	2/18/1789		C4.35.jpg	Slate	22x2x37
C4.33	Headstone	143	Bucknam	Reb??	7/20/1772		C4.33.jpg	Slate	23x2
C4.34	Footstone	143.1	Bucknam	Reb??			C4.34.jpg	Slate	
C4.31	Headstone	144	Bucknam	Edward	5/14/1773		C4.31.jpg	Slate	23x2x27
C4.32	Footstone	144.1	Bucknam	Edward			C4.32.jpg	Slate	
C4.29	Headstone	145	Gould	Mary	5/26/1793		C4.29.jpg	Slate	22x2x29
C4.30	Footstone	145.1	Gould	Mary			C4.30.jpg	Slate	
C4.27	Headstone	146	Gould	Moley	1/6/1787		C4.27.jpg	Slate	22x1x28
C4.28	Footstone	146.1	Gould	Moley			C4.28.jpg	Slate	
C4.25	Headstone	147	Gould	Mary	4/9/1771		C4.25.jpg	Slate	29.5x1.5x28
C4.26	Footstone	147.1	Gould	Mary			C4.26.jpg	Slate	
C4.23	Headstone	148	Gould	Abraham	1/9/1821		C4.23.jpg	Slate	27x1.5x49
C4.24	Footstone	148.1	Gould	Abraham			C4.24.jpg	Slate	
C4.21	Headstone	149	Gould	Tabitha	4/5/1831		C4.21.jpg	Slate	25.5x2x48
C4.22	Footstone	149.1	Gould	Tabitha			C4.22.jpg	Slate	
C4.20	Headstone	150	Hay	Isabel	3/15/1786		C4.20.jpg	Slate	22x1.5x33
E5.02	Headstone	151	Richardson	Oliver	??		E5.02.jpg	Marble	22x2x17
D5.14	Headstone	152	Winslow	Philena	3/21/1882		D5.14.jpg	Marble	22x5x39
D5.13	Headstone	153	Green	Jesse	10/20/1868		D5.13.jpg	Marble	24x4x48
D5.11	Headstone	154	Green	Jerusha	9/5/1775		D5.11.jpg	Slate	23x1,5x24

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription Photo	Stone	Size (inches)
D5.12	Footstone	154.1	Green	Jerusha		D5.12.jpg	Slate	
D5.09	Headstone	155	Green	John	1/30/1774	D5.09.jpg	Slate	25x1.5x30
D5.10	Footstone	155.1	Green	John		D5.10.jpg	Slate	
D5.07	Headstone	156	Gerry	Sarah	1/14/1839	D5.07.jpg	Slate	24x1.5x46
D5.08	Footstone	156.1	Gerry	Sarah		D5.08.jpg	Slate	
D5.05	Headstone	157	Geary	David	3/17/1807	D5.05.jpg	Slate	25x3x46
D5.06	Footstone	157.1	Geary	David		D5.06.jpg	Slate	
C5.04	Headstone	158	Geary	Anna	6/5/1790	C5.04.jpg	Slate	24x3x39
C5.05	Footstone	158.1	Geary	Anna		C5.05.jpg	Slate	
C5.03	Headstone	159	Simonds	Nathan	7/30/1795	C5.03.jpg	Slate	16.5x1.5x36
C5.02	Headstone	160	Simonds	Abigail	3/21/1860	C5.02.jpg	Slate	18x2xna
C5.01	Headstone	161	Simonds	Nabby	??	C5.01.jpg	Marble	18x3x40
B4.03	Headstone	162	Crooker	Polly	9/16/1793	B4.03.jpg	Slate	
E5.01	Headstone	163	Richardson	Betsy	??	E5.01.jpg	Slate	24x2x27
D5.19	Headstone	164	Richardson	Oliver	10/5/1802	D5.19.jpg	Slate	21x3x19
D5.18	Headstone	165	Richardson	Mary	4/12/1824	D5.18.jpg	Slate	24x1.5x41
D5.17	Headstone	166	Richardson	Oliver	5/2/1827	D5.17.jpg	Slate	25x1.5x45
D5.15	Headstone	167	Richardson	Betty	2/28/1805	D5.15.jpg	Slate	22.5x2.5x36
D5.16	Footstone	167.1	Richardson	Betty		D5.16.jpg	Slate	
D5.04	Headstone	168	Gerry	(children)	??	D5.04.jpg	Marble	13x1.5x17
D5.03	Headstone	169	Gerry	Lucunda & Abig	2/5/182?	D5.03.jpg	Marble	12x2x18
C5.06	Headstone	170	Geary	Lucinda	6/11/1808	C5.06.jpg	Slate	19x2x36
C5.07	Headstone	171	Gary	Abner	4/20/1837	C5.07.jpg	Slate	22x1.5x37
C5.08	Headstone	172	Gerry	Minerva	9/12/1878	C5.08.jpg	Marble	24x3x51
C5.09	Headstone	173	Gerry	Elbridge	12/18/1868	C5.09.jpg	Marble	24x3x49
C5.10	Headstone	174	Gerry	William	??	C5.10.jpg	Marble	24x2x48
C5.11	Headstone	175	Bucknam	Mary	6/3/1847	C5.11.jpg	Slate	21x2x51
C5.12	Headstone	176	Bucknam	Phebe	5/5/1825	C5.12.jpg	Slate	20x1.5x38

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C5.13	Headstone	177	Bucknam	Nathan	5/26/1847		C5.13.jpg	Slate	21x2x49
C5.14	Headstone	178	Bucknam	Abigail	6/3/1816		C5.14.jpg	Slate	21x1.5x41
B5.01	Headstone	179	Gerry	Persis	9/5/182?		B5.01.jpg	Slate	23.5x1.5x44
D5.02	Headstone	180	Richardson	Jonas	3/24/1796		D5.02.jpg	Slate	16x1.5x27
D5.01	Headstone	181	Pool	Anna	11/21/1818		D5.01.jpg	Slate	21x1.5x34
C5.15	Headstone	182	Holden	Ebenezer	8/26/1813		C5.15.jpg	Sandstone	17x2x22
C5.16	Headstone	183	Hadley	Daniel	9/17/1822		C5.16.jpg	Slate	18x1.5x28
C5.17	Headstone	184	Gerry	Lizzie	12/12/1913		C5.17.jpg	Marble	22x2x54
C5.18	Headstone	185	Gerry	Sally	??		C5.18.jpg	Marble	22x2x52
C5.19	Headstone	186	Gerry	Arad	3/23/1833		C5.19.jpg	Marble	21x2x48
D6.03	Headstone	187	Piper	Mary	11/7/1839		D6.03.jpg	Slate	24x2x59
D6.02	Headstone	188	Barnes	Sarah	1854		D6.02.jpg	Marble	12x3x8
D6.01	Headstone	189	Barnes	Daniel	1886		D6.01.jpg	Marble	12x3x10
C6.06	Headstone	190	Barnes	Robert	8/3/1826		C6.06.jpg	Marble	22x2x38
C6.05	Headstone	191	Barnes	Anna	8/16/1829		C6.05.jpg	Marble	20x2x33
C6.03	Headstone	192	Howard	Joshua	??		C6.03.jpg	Marble	
C6.04	Footstone	192.1	Howard	Joshua			C6.04.jpg	Marble	
C6.01	Headstone	193	Howard	Elizabeth	8/31/1839		C6.01.jpg	Marble	21x2x45
C6.02	Footstone	193.1	Howard	Elizabeth			C6.02.jpg	Marble	
C6.07	Headstone	195	Cleaves	Anna & infant	4/12/1843		C6.07.jpg	Slate	32x1.5x60
C6.08	Footstone	195.1	Cleaves	Anna & infant			C6.08.jpg	Slate	
B5.02	Headstone	196	Wardwell	Sarah	5/17/1854		B5.02.jpg	Marble	20x2x25
B5.03	Headstone	197	Wardwell	??	??		B5.03.jpg	Marble	Fragment
B5.04	Headstone	198	Wiley	Susannah	8/3/1841		B5.04.jpg	Slate	22x2x35
B5.05	Headstone	199	Wiley	Phinehas	11/21/1831		B5.05.jpg	Slate	22x1.5x39
B5.06	Headstone	200	Wiley	Sally	8/16/1835		B5.06.jpg	Slate	21x1x40
B5.07	Headstone	201	Wiley	William	8/11/1831		B5.07.jpg	Slate	21x1x40
B5.08	Headstone	202	Wiley	Harriet	6/9/1825		B5.08.jpg	Slate	20x1.5x30

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
B5.09	Headstone	203	Wiley	Sophia	12/18/1824		B5.09.jpg	Slate	20x1.5x35
B6.01	Headstone	204	Hay	Rebecca	7/17/1843		B6.01.jpg	Slate	27x2x46
B6.02	Headstone	205	Hay	Peter	3/3/1810		B6.02.jpg	Slate	27x1.5x42
B6.03	Headstone	206	Hay	Dorcas	5/26/1813		B6.03.jpg	Slate	20x1.5x32
B6.04	Headstone	207	Hay	David	6/1/1828		B6.04.jpg	Slate	
B6.05	Headstone	208	Hay	Aaron	9/28/1841		B6.05.jpg	Slate	23x55
B6.08	Headstone	209	Willy	George	12/9/1803		B6.08.jpg	Slate	22.5x1.5x39
B6.09	Headstone	210	Willy	Nathan	4/28/1807		B6.09.jpg	Slate	20x1.5x39
B6.10	Headstone	211	Willey	Precilla	5/8/1834		B6.10.jpg	Slate	19.5x1.5x38
B6.11	Headstone	212	??	??	3/27/??		B6.11.jpg	Marble	
B6.12	Headstone	213	Willy	James	1/26/1825		B6.12.jpg	Slate	20x2x40
B6.13	Headstone	214	Barnes	Aaron	8/25/1825		B6.13.jpg	Slate	15x1.5x25
B5.10	Headstone	215	Wiley	Sally	8/5/1836		B5.10.jpg	Slate	21x1.5x35
B5.11	Headstone	216	Wiley	William	1/28/1846		B5.11.jpg	Slate	18x1.5x31
B6.06	Headstone	217	Hay	William/Betsy	816;8/3/1815		B6.06.jpg	Slate	22.5x2x28
B6.07	Footstone	217.1	Hay	William/Betsy			B6.07.jpg	Marble	
B6.14	Headstone	219	Hay	Mary	12/27/1865		B6.14.jpg	Slate	30x2x55
B6.15	Footstone	219.1	Hay	Mary			B6.15.jpg	Slate	
B6.16	Headstone	220	Hay	Peter	4/12/1845		B6.16.jpg	Slate	27x2x51
B6.17	Footstone	220.1	Hay	Peter			B6.17.jpg	Slate	
B6.18	Headstone	221	Hay	Peter	1/15/1841		B6.18.jpg	Slate	26.5x2x49
B6.19	Footstone	221.1	Hay	Peter			B6.19.jpg	Slate	
B6.20	Headstone	222	Hay	(3 infants)	multiple		B6.20.jpg	Slate	17.5x2x40
B7.01	Headstone	223	Wright	Peter	3/2/1827		B7.01.jpg	Slate	25x1.5x40
B7.02	Footstone	223.1	Wright	Peter			B7.02.jpg	Slate	
B7.03	Headstone	224	Wright	Peter	12/30/1803		B7.03.jpg	Slate	24x3.5x30
B7.04	Footstone	224.1	Wright	Peter			B7.04.jpg	Slate	
B7.05	Headstone	225	Wright	Timothy	4/28/1828		B7.05.jpg	Slate	14.5x1.5x22

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
B7.06	Footstone	225.1	Wright	Timothy			B7.06.jpg	Slate	
B7.07	Headstone	226	Wright	Persis	6/12/1831		B7.07.jpg	Slate	22x2x37
B7.08	Headstone	227	Eames	Ruth	12/21/1838		B7.08.jpg	Marble	20x2x40
B7.09	Headstone	228	Wright	Elizabeth	9/3/1845		B7.09.jpg	Slate	22x2x34
B7.10	Footstone	228.1	Wright	Elizabeth			B7.10.jpg	Slate	
B7.11	Headstone	229	Eames	Lovina	9/28/1847		B7.11.jpg	Marble	20x1.5x32
B7.12	Headstone	230	Richardson	Caleb	11/22/1815		B7.12.jpg	Slate	27x2x44
B7.13	Footstone	230.1	Richardson	Caleb			B7.13.jpg	Slate	
B7.14	Headstone	231	Richardson	Sally	6/21/1811		B7.14.jpg	Slate	27x1.5x14
B7.15	Footstone	231.1	Richardson	Sally			B7.15.jpg	Slate	
B8.01	Headstone	232	Richardson	Mary	1/22/1803		B8.01.jpg	Slate	20x2.5x26
B8.02	Footstone	232.1	Richardson	Mary			B8.02.jpg	Slate	
B8.04	Headstone	233	Richardson	Sarah	12/3/1812		B8.04.jpg	Slate	29x2x41
B8.05	Footstone	233.1	Richardson	Sarah			B8.05.jpg	Slate	
B8.06	Headstone	234	Richardson	Caleb	4/4/1814		B8.06.jpg	Slate	28.5x1.5x37
B8.07	Footstone	234.1	Richardson	Caleb			B8.07.jpg	Slate	
B8.08	Headstone	235	Richardson	Rufus	2/9/1831		B8.08.jpg	Slate	24x2.5x41
B8.09	Headstone	236	Richardson	Anna	9/5/1808		B8.09.jpg	Slate	21x2x42
B8.10	Footstone	236.1	Richardson	Anna			B8.10.jpg	Slate	
B8.11	Headstone	237	Richardson	Anna	6/16/1802		B8.11.jpg	Slate	14.5x1x24
B8.12	Headstone	238	Ingols	Ruth	5/25/1790		B8.12.jpg	Slate	24.5x2.5x30
B7.16	Headstone	239	Arnold	Artemas	1868		B7.16.jpg	Marble	12x4x11
B7.17	Footstone	239.1	Arnold	Artemas			B7.17.jpg	Marble	
B7.18	Headstone	240	Bray	Hannah	??		B7.18.jpg	Marble	12x4x12
B7.19	Footstone	240.1	Bray	Hannah			B7.19.jpg	Marble	
B7.20	Headstone	241	Hadley	Rebekah	7/16/1812		B7.20.jpg	Slate	12x1x16
B7.21	Headstone	242	Hadley	Hannah	5/17/1807		B7.21.jpg	Slate	17x1x25
B7.22	Headstone	243	Hadley	Hannah	5/1/1818		B7.22.jpg	Slate	20x1.5x29

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription Photo	Stone	Size (inches)
B7.23	Footstone	243.1	Hadley	Hannah		B7.23.jpg	Slate	
B7.24	Headstone	244	Green	Daniel	1/5/1842	B7.24.jpg	Slate	24x2x45
B7.25	Footstone	244.1	Green	Daniel		B7.25.jpg	Slate	
B7.26	Headstone	245	Green	Polley	9/9/1837	B7.26.jpg	Slate	24x2x45
B7.27	Footstone	245.1	Green	Polley		B7.27.jpg	Slate	
B7.28	Headstone	246	Green	Sarah	5/8/1806	B7.28.jpg	Slate	24.5x1.5x41
B7.29	Footstone	246.1	Green	Sarah		B7.29.jpg	Slate	
B8.03	Headstone	247	Green	Samuel	8/31/1871	B8.03.jpg	Marble	22x3x38
B8.13	Headstone	248	Vinton	Ezra	11/11/1817	B8.13.jpg	Slate	31x2x55
B8.14	Headstone	249	Vinton	Sarah	8/31/1829	B8.14.jpg	Slate	23x2.5x52
B8.15	Headstone	250	Vinton	Isaac	8/10/1865	B8.15.jpg	Marble	18x3x40
B8.17	Headstone	251	Green	Thomas	10/1/1842	B8.17.jpg	Slate	24x2x38
B8.18	Headstone	252	Green	Anna	7/5/1813	B8.18.jpg	Slate	19x1.5x38
B7.30	Headstone	253	Bryant	Harriet	1/21/1843	B7.30.jpg	Slate	15x2x29
B7.31	Headstone	254	Hill	James	5/26/1834	B7.31.jpg	Slate	22x2x44
B7.32	Headstone	255	Hill	Mary	2/20/1810	B7.32.jpg	Slate	22x2x32
B8.19	Headstone	256	Rowe	Phebe	1/22/1826	B8.19.jpg	Slate	17x2x30
B8.20	Headstone	257	Rowe	Louiza	11/1/1830	B8.20.jpg	Slate	16x2x27
B8.21	Headstone	258	Rowe	Maria	5/28/1836	B8.21.jpg	Slate	17x1.5x30
B8.22	Headstone	259	Lynde	Sarah	7/29/1838	B8.22.jpg	Slate	22x1.5x40
B8.23	Headstone	260	Lynde	Horace	8/19/1837	B8.23.jpg	Slate	15x1x18
B8.24	Headstone	261	Green	Henry/Abigail	??/9/16/1869	B8.24.jpg	Marble	12x4.5x40
B8.25	Headstone	262	Green	Mother B.S.G.	??	B8.25.jpg	Marble	13.5x3x9
B8.26	Headstone	263	Green	Father H.G.	??	B8.26.jpg	Marble	13.5x3x9
B8.27	Headstone	264	Green	Mother A.G.G.	??	B8.27.jpg	Marble	13.5x3x9
B8.28	Headstone	265	Green	Fidelia	??	B8.28.jpg	Marble	13.5x9x3
B9.01	Headstone	266	Crooker	Lydia	6/17/1824	B9.01.jpg	Slate	19x1.5x35
C7.01	Headstone	267	Bryant	Ebenezer	12/12/1862	C7.01.jpg	Marble	15x2x35

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C7.02	Headstone	268	Bryant	Sophia	9/21/1875		C7.02.jpg	Marble	15x2x35
C7.03	Headstone	269	Bryant	Sarah	3/31/1832		C7.03.jpg	Slate	15x2x29
C7.04	Headstone	270	Hill	Levi	12/1/1829		C7.04.jpg	Slate	15x1.5x26
C7.05	Headstone	271	Howard	John	4/15/1824		C7.05.jpg	Slate	19x1.5x42
C8.01	Headstone	272	Howard	Sarah/Mary	2/17/1820		C8.01.jpg	Marble	16x4x11
C8.02	Headstone	273	Lynde	Jabez	3/30/1835		C8.02.jpg	Marble	22x2x43
C8.03	Headstone	274	Lynde	Hepsibah	5/1/1839		C8.03.jpg	Marble	22x2x46
C8.04	Headstone	275	Lynde	Sarah	1924		C8.04.jpg	Marble	24xnax47
C8.05	Headstone	276	Lynde	Moses/Warren	3/34;8/29/1834		C8.05.jpg	Marble	21x2x24
C8.06	Headstone	277	Lynde	George	5/27/1835		C8.06.jpg	Marble	16x2x24
C8.07	Headstone	278	??	Sarah	??		C8.07.jpg	Marble	
C8.08	Headstone	279	Lynde	Otis	5/16/1862		C8.08.jpg	Marble	18x3x37
C8.09	Headstone	280	Lynde	Charles	10/4/1870		C8.09.jpg	Marble	18x3x37
C8.10	Headstone	281	Cary	Kesiah	3/28/1863		C8.10.jpg	Marble	15x2x28
B9.02	Headstone	282	Colesworthy	AnnMaria	2/13/1830		B9.02.jpg	Slate	20x1.5x37
C7.06	Headstone	283	Hill	Lavina/Emma	4/20/1849		C7.06.jpg	Marble	18x2x29
C7.07	Headstone	284	??	Nancy	??		C7.07.jpg	Marble	10x1.5x13
C7.08	Headstone	285	Woodward	Marcus	3/1/1863		C7.08.jpg	Marble	20x2x40
C7.09	Headstone	286	Bryant	Nancy	11/2/1817		C7.09.jpg	Slate	21x2x39
C7.10	Footstone	286.1	Bryant	Nancy			C7.10.jpg	Slate	
C7.11	Headstone	287	Bryant	Elias	3/25/1834		C7.11.jpg	Slate	23x2x44
C7.12	Headstone	288	Bryant	Joseph	10/5/1818		C7.12.jpg	Slate	15x1.5x24
C8.11	Headstone	289	Green	Lavina	1898		C8.11.jpg	Marble	18x5x24
C9.01	Headstone	290	Williams	Phebe	??		C9.01.jpg	Marble	13x3x9.5
C7.13	Headstone	291	Prentiss	Hannah	9/24/1829		C7.13.jpg	Slate	20x2x35
C8.12	Headstone	292	Messer	Woodbury	3/2/1843		C8.12.jpg	Slate	22x2x41
C8.13	Headstone	293	Messer	Elizabeth	1879		C8.13.jpg	Marble	18x5x24
C9.04	Headstone	294	Hill	James	10/24/1807		C9.04.jpg	Slate	26x2x55

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
C9.05	Footstone	294.1	Hill	James			C9.05.jpg	Slate	
C9.02	Headstone	295	Hill	Elizabeth	1/19/1822		C9.02.jpg	Slate	31x1.5x54
C9.03	Footstone	295.1	Hill	Elizabeth			C9.03.jpg	Slate	
C7.15	Headstone	296	Green	Susan	10/28/1831		C7.15.jpg	Slate	22x2x38
C7.16	Headstone	297	Vinton	??	??		C7.16.jpg	Marble	n.a.
C8.15	Headstone	298	Wilson	William	11/6/1827		C8.15.jpg	Slate	28x1.5x54
C8.14	Headstone	299	Derby	Abigail	7/15/1845		C8.14.jpg	Slate	18x2x45
D7.01	Headstone	300	Rockwell	Lucy	6/5/1839		D7.01.jpg	Marble	24x2x51
D7.02	Headstone	301	Burnham	Joshua/Lois	810;3/4/1827		D7.02.jpg	Marble	26x1.5x38
D8.01	Headstone	302	Stone	Lydia	2/28/1831		D8.01.jpg	Slate	21x1.5x39
D8.02	Headstone	303	Stone	Lydia	3/10/1827		D8.02.jpg	Slate	
D8.03	Footstone	303.1	Stone	Lydia			D8.03.jpg	Slate	
D8.04	Headstone	304	Stone	William	6/14/1822		D8.04.jpg	Slate	15x1.5x27
D8.05	Headstone	305	Stone	Joseph	5/12/1834		D8.05.jpg	Slate	15x1.5x23
D8.06	Footstone	305.1	Stone	Joseph			D8.06.jpg	Slate	
D8.07	Headstone	306	Cowdrey	John	1/20/1829		D8.07.jpg	Slate	23x1.5x33
D8.08	Footstone	306.1	Cowdrey	John			D8.08.jpg	Slate	
D8.09	Headstone	307	Cowdrey	Sarah	9/15/1825		D8.09.jpg	Slate	20.5x1.5x41
D8.10	Headstone	308	Cowdrey	Betsey	10/12/1828		D8.10.jpg	Slate	15x1x23
C9.07	Headstone	309	Richardson	Sally	12/29/1876		C9.07.jpg	Slate	23x2x44
C9.08	Footstone	309.1	Richardson	Sally			C9.08.jpg	Slate	
D9.01	Headstone	310	Brown	Jacob	11/20/1827		D9.01.jpg	Slate	20x1.5x36
D9.02	Headstone	311	Gerry	Simeon	1/28/1828		D9.02.jpg	Slate	20x1.5x37
D9.03	Footstone	312	? (n.a.)	(n.a.)			D9.03.jpg	Marble	
D9.04	Footstone	312.1	?(A.A.)				D9.04.jpg	Marble	
D7.03	Headstone	313	Newhall	Mary	1/16/1858		D7.03.jpg	Marble	21.5x2x46
D7.04	Headstone	314	Newhall	Clarissa	1/7/1887		D7.04.jpg	Marble	22x2x49
C7.14	Headstone	315	Larrabee	Hannah	3/2/1826		C7.14.jpg	Slate	25x1.5x51

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription Photo	Stone	Size (inches)
D8.11	Headstone	316	Stone	Aaron		D8.11.jpg	Marble	
D8.11.1	Headstone	316	Stone	Clarissa		D8.11.jpg	Marble	
D7.05	Headstone	317	Green	Sarah	10/13/1861	D7.05.jpg	Marble	18x2x34
D7.06	Headstone	318	Green	William	9/7/1843	D7.06.jpg	Slate	21x1.5x47
D7.07	Headstone	319	Green	Abigail	11/6/1848	D7.07.jpg	Slate	23.5x2.5x46
D8.13	Headstone	320	Green	Jonathan	10/8/1811	D8.13.jpg	Marble	20x2x38
D8.14	Headstone	321	Green	Susanna	5/1/1861	D8.14.jpg	Marble	20x2x36
D8.12	Headstone	322	Tuttle	Eunice	2/28/1832	D8.12.jpg	Slate	20.5x1.5x37
D8.25	Headstone	323	Locke	Polly/Lucinda	320;5/11/1817	D8.25.jpg	Slate	22x2x29
D8.26	Headstone	324	Pierce	Timothy	3/9/1840	D8.26.jpg	Slate	26x2x52
D8.27	Headstone	325	Pierce	William	7/3/1832	D8.27.jpg	Slate	23x1.5x43
D7.08	Headstone	326	??			D7.08.jpg	Slate	
D7.09	Headstone	327	Hill	Lydia	8/1/1896	D7.09.jpg	Slate	30.5x2x58
D7.10	Headstone	328	Hill	John	3/28/1858	D7.10.jpg	Slate	30.5x2
D7.11	Headstone	329	Hill	Rebecca	9/21/1828	D7.11.jpg	Slate	30.5x2x61
D7.12	Headstone	330	Hill	John/Rebekah	318;7/31/1820	D7.12.jpg	Slate	22x2x28
D7.13	Headstone	331	Green	Peter	5/7/1861	D7.13.jpg	Marble	20x1.5
D7.14	Headstone	332	Green	Lydia	12/23/1840	D7.14.jpg	Slate	22x2x46
D7.15	Footstone	332.1	Green	Lydia		D7.15.jpg	Slate	
D7.16	Headstone	333	Cass	Lydia	12/23/1846	D7.16.jpg	Slate	25x1.5x47
D7.17	Footstone	333.1	Cass	Lydia		D7.17.jpg	Slate	
D7.18	Headstone	334	Green	Rebekah	4/5/1831	D7.18.jpg	Marble	26x2x54
D7.19	Footstone	334.1	Green	Rebekah		D7.19.jpg	Marble	
D8.15	Headstone	335	??			D8.15.jpg	Marble	16x1.5x27
D8.16	Footstone	335.1	??			D8.16.jpg	Marble	
D8.17	Headstone	336	Green	Cordelia	8/23/1887	D8.17.jpg	Marble	20.5x2x40
D8.18	Headstone	337	Green	Rebekah	4/23/1823	D8.18.jpg	Slate	21x1.5x37
D8.19	Footstone	337.1	Green	Rebekah		D8.19.jpg	Slate	

Stoneham Old Burying Ground
GRAVESTONE INVENTORY - 2012

Location	Type	ID	Last Name	First Name	D.O.D.	Inscription	Photo	Stone	Size (inches)
D8.20	Headstone	338	Hosmer	Elijah	3/24/1810		D8.20.jpg	Slate	18x1.5x31
D8.21	Footstone	338.1	Hosmer	Elijah			D8.21.jpg	Slate	
D8.22	Headstone	339	Rowe	William	7/16/1830		D8.22.jpg	Marble	20x2x47
D8.23	Headstone	340	Rowe	Susannah	4/4/1847		D8.23.jpg	Marble	20x2x44
D8.24	Headstone	341	Rowe	Pamela	8/5/1806		D8.24.jpg	Slate	19.5x1.5x38
D9.06	Headstone	342	Pierce	Ephraim	5/15/1810		D9.06.jpg	Slate	25x2x41
D9.07	Footstone	342.1	Pierce	Ephraim			D9.07.jpg	Slate	
D9.08	Headstone	343	Pierce	Abigail	1/9/1840		D9.08.jpg	Slate	24x1.5x43
D9.09	Headstone	344	Pierce	Samuel	4/24/1813		D9.09.jpg	Slate	25.5x1.5x37
D9.10	Footstone	344.1	Pierce	Samuel			D9.10.jpg	Slate	
D9.05	Headstone	345	Brown	Laura/Susan	320;9/25/1820		D9.05.jpg	Slate	27x2x26
B8.16	Headstone	346	Vinton	Mary	?		B8.16.jpg	Marble	18x3x40
C3.28	Headstone	347	Parker	Ruth	6/26/1749		C3.28.jpg	Slate	17x1.5x24
C3.27	Headstone	348	Hill	James	7/17/1745		C3.27.jpg	Slate	19x3x25

